



## ***DECLARATION OF CONFORMITY***

***With regard to the Electromagnetic Compatibility Directive 89/336/EEC  
and  
Low-voltage Directive 73/23/EEC and the Amendment Directive 93/68/EEC***

### **Cisco-Linksys LLC**

121 Theory Drive  
Irvine, CA 92617  
USA

Declares under our sole responsibility that the product,

### ***Linksys SPA3102 / Voice Gateway with Router***

***Variants: SPA3102 – XX where XX may stand for BG, BT, DE,FR, EU, E1, SE or UK (where applicable)***

Fulfills the essential requirements of Directive 89/336/EEC

The following standards were applied:

<b>EMC</b>	<b>EN 55022:1998 + A1:2000 + A2:2003</b>
	<b>EN 55024: 1998 + A1:2001 + A2:2003</b>
<b>Safety</b>	<b>EN 60950-1:2001</b>

Note : This declaration is only valid for configurations (combinations of software, firmware and hardware) provided and/or supported by Linksys. The use software or firmware not supported/provided by Linksys may result that the equipment is no longer compliant with the regulatory requirements.

The product carries the CE Mark:



Date & Place of Issue: **26 January, 2006** – The Netherlands

**Signature:**

**Ivar Beljaars**  
**EMEA Product Manager & Systems Engineer**  
Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam Netherlands

Additional Information:

EMC Test Report  
Safety Test Report

*Advance Data Technology Corporation Test Report Number: CE941223H08; 24 January, 2006*  
*PSB Corporation Pte. Ltd. ; Test Report Number : 55S060523/CZ/MNG ;02, March, 2006*